

CD Self-Assessment  
FCC Emergency Lights

During the October, 2011 planned electrical shutdown of FCC, the building's emergency lights were inspected to ensure that they were working properly and that there were an appropriate number to provide adequate lighting during an emergency.

Prepared By: Amy Pavnica

Date: October 18, 2011

Approved By: \_\_\_\_\_

Date: 10-21-2011

Approved By: \_\_\_\_\_

Date: 10-21-2011

October 18, 2011

## CS Self-Assessment

### FCC Emergency Lights

On October 15, 2011, the Feynman Computer Center had a planned electrical shutdown of all the building power. The only exception was that the third floor computer center remained powered up. The shutdown of the rest of the building occurred for maintenance and upgrade reasons.

The shutdown occurred at 6:25 am, before sunrise. Within the first hour, the entire building was walked through, focusing on emergency lighting. The following was noted.

- The south end of the FCC2 Computer Room was very dark. There are no emergency lights at this end of the computer room.
- The FCC2 orange hallway was completely dark. No emergency lights.
- There are no emergency lights at the south end of the FCC2 cubical area.
- In the rear stairwell, it was dark on the 3<sup>rd</sup> floor platform. There is no emergency light on this platform or the 3 ½ floor platform (leading up to the roof).
- The emergency light on the rear stairwell (2 ½ floor) was very dim.
- The emergency light outside of the PREP area was not working.
- There is no emergency light in the small battery room off of the rear corridor.

These findings are entered into frESHTRK, and the building management has been notified.